



**Correctly protected threshold:**

Ramp is not in contact with the door threshold.



# Protecting your Windows & Doors during the Building Process



**Correctly prepared opening:**

Sill in place and free of debris, DPC present and correctly positioned, block work straight and neat.

Form No: 243



Charlestown, Co. Mayo, Ireland  
Locall  
Republic of Ireland 1890 411 411  
Northern Ireland 0871 998 7080  
tel +353 (0)94 929 1000 fax: +353 (0)94 9254 355

Swift Print & Design 1890 500507



The following building practises will generate product related issues that are not covered under your Grady Joinery warranty agreement.

**Plaster on window & handles:**

Plaster will harden onto handles, PVC, Timber and exposed glass and result in permanent marks and scratches. See Maintenance Guide Section 4.



**Threshold not protected:**

Door frame will be distorted/ moved and result in the door not closing correctly. The door will, at minimum, require re-adjusting and in worst case scenarios require replacing. Threshold should be protected at all times during building process. Issue may only come to light at a later date.



**Debris in Window Channel:**

Window locks and hinges will be damaged. Grit will get between moving parts. The window will at minimum, not close correctly and in worst case scenarios require replacing. Windows and doors should be kept shut during all stages of the building process.



**Care and attention:** Product is damaged beyond repair and will need to be replaced.



**Site management:** Storage of debris results in damage to product. Building material should never be passed through open windows.



**Building material stacked against window & doors:**

Glass, PVC, Timber and handles will be permanently marked and scratched.

